


To convert feet to meters
multiply feet by 0.3048.



This report has not been edited
for conformity with U.S. Geological
Survey editorial standards or
stratigraphic nomenclature.

BY
IntraSearch
1978

PLATE 26
ISOPACH MAP OF OVERBURDEN
AND INTERBURDEN OF
WALL-PAWNEE COAL ZONE